



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: *IFCC 1265*

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

David Smith St Ives Limited

Marley Road
St Ives
Huntingdon
Cambridgeshire PE27 3EX
01480 309900
doors@davidsmith.co.uk

Who fabricate the following timber fire doors and or doorsets:

**DSF (FD30, FD60), DSP (FD30, FD60, FD90, FD120),
DST (FD30, FD60, FD90),
DSTm (FD30, FD60), DSA (FD30, FD60, FD90)
and DSXL (FD30, FD60) Flush Doors**

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve for **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



First Issued: 25 October 2016
Reissued: 28 October 2021
Valid to: 24 October 2026
Issue No: 4

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1265

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
DSF	FD30, FD60	IFCC1265-DSF01
DSP	FD30, FD60, FD90, FD120	IFCC1265-DSP02
DST	FD30, FD60	IFCC1265-DST03
DSTm	FD30, FD60	IFCC1265-DSTm04
DSA	FD30, FD60, FD90	IFCC1265-DSA05
DSXL	FD30, FD60	IFCC1265-DSXL07

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.